



**Removal of Fiberglass from Hull**



**Removal of Hull Coating**



**Evaluating Deconstruction**





**Removal of Inner Hull Coating**



**Refinished Inner Hull**



**Reconstruction of Interior  
Support Structure**



**Attaching Interior Handholds**





**Interior Reconstruction**





**Rigger Mounting Plugs**



**Sanding Outer Hull**



**Applying Fiberglass to Outer Hull**



**Preparing to Apply Varnish to Fiberglass**





**Repaired Fin Box**



**Fitting of the Fin**



**Internal Support Structure**




**Installation of Seat Rails and Seats**





**Seat rails and Seats Installed**



**Bracing and Forms for Hull Repair**



**Realignment Preparation**



**Realignment Result**





**Bow Deck Structure**



**Placing Dacron for Bow Deck**



**Burnishing Bow Deck**



**Ironing Dacron Deck**





**Varnished Bow Deck**



**Burnishing Stern Deck**



**Stern Deck**




**Naming Restored Boat in Honor of Jim Buckley**





**Custom Inspection/Drying Portal**



**3D Printer/Fabricator**

